



3M Automotive Aftermarket Division

Third Party Recommendations, Approvals, & Endorsements



Driving the Power of 3M Innovation into Every Repair



Everyday, engineers and technicians around the world choose 3M products as the best solution for their manufacturing and repair needs. From Specifications and Endorsements to Service Bulletins and Recall Notices, 3M is proud to be a trusted partner of the Automotive Industry.

Here's just one example...



Reference Information

Organization: American Honda Motor Co. Inc.

Document

Type: Service Bulletin
Name: Upper B-Pillar or Moonroof Area Clicks, Rattles, or Taps
Number: 11-027
Issued: August 7, 2012

Description

Vehicles: 2009-11 Acura TL: ALL
2012 Acura TL 2WD: From 19UUA8...CA000001 thru 19UUA8...CA030468
2012 Acura TL SH-AWD: From 19UUA9...CA000001 thru 19UUA9...CA009652

Purpose: Symptom:
The upper B-Pillar or moonroof area clicks, rattles, or taps on one or both sides.

Probable Cause:
There is insufficient clearance between the metal body panels in the upper B-Pillar area.

Corrective Action:
Depending on the source of the noise, add sealer between the body panels, or increase the clearance between the body panels.

Note: 3M provides this information for REFERENCE ONLY.
ALWAYS refer to the original document or the OEM-provided model-specific collision damage repair manuals for complete instructions.

3M Products:

Included:	PN08360	3M™ Urethane Seam Sealer Sachet – White
	PN08362	3M™ Urethane Seam Sealer Cartridge – Grey
	PN08365	3M™ Urethane Seam Sealer Cartridge – Beige
	PN08367	3M™ Urethane Seam Sealer Cartridge – Black
	PN08368	3M™ Urethane Seam Sealer Cartridge – White

Note: In some cases, 3M may offer an alternate part number (different size/color) with the same chemistry and/or performance as the included product. Please consult your 3M Representative for more information.

Source:

www.TechInfo.Acura.com
www.Collision.ALLDATA.com

Product Use:

Many factors beyond 3M's control and uniquely within user's knowledge and control can affect the use and performance of a 3M product in a particular application. Given the variety of factors that can affect the use and performance of a 3M product, user is solely responsible for evaluating the 3M product and determining whether it is fit for a particular purpose and suitable for user's method of application.

Warranty, Limited Remedy, and Disclaimer:

Unless an additional warranty is specifically stated on the applicable 3M product packaging or product literature, 3M warrants that each 3M product meets the applicable 3M product specification at the time 3M ships the product. 3M MAKES NO OTHER WARRANTIES OR CONDITIONS, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OR CONDITION OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR ANY IMPLIED WARRANTY OR CONDITION ARISING OUT OF A COURSE OF DEALING, CUSTOM OR USAGE OF TRADE. If the 3M product does not conform to this warranty, then the sole and exclusive remedy is, at 3M's option, replacement of the 3M product or refund of the purchase price.

Limitation of Liability:

Except where prohibited by law, 3M will not be liable for any loss or damage arising from the 3M product, whether direct, indirect, special, incidental or consequential, regardless of the legal theory asserted, including warranty, contract, negligence or strict liability.



Automotive

Aftermarket Division
Building 0223-06-N-01
St. Paul, MN 55144-1000
3MCollision.com

3M is a trademark of 3M.
Please Recycle. Printed in the U.S.A.
© 3M 2012. All rights reserved.
1-877-MMM-CARS (877-666-2277)