


800.633.3047

**AIRLESS REPLACEMENT ELEMENTS**

- 5500-C Retro Fit Kit - For making 6012 compatible with Model 3,4 and 5 welders.
- 6012 200 Watt 120V Ceramic Core Replacement Element Assembly (For MiniWeld Model 6 or 7).
- 6012-P Same as 6012 with USA plug.
- 6012-240 200 Watt 240V Ceramic Core Replacement Element Assembly (For MiniWeld Model 6 or 7 EUR and Model 6 or 7 AUS).
- 6012-EUR 200 Watt 240V Ceramic Core Element Assembly with European Schuko plug.
- 6012-AUS Same as 6012 with Australian plug.
- 6012C 200 Watt 120V Replacement Ceramic Core for 6012 and 6012-P.
- 6012C-240 200 Watt 240V Replacement Ceramic Core for 6012-EUR and 6012-AUS.



**AIRLESS WELDER PARTS**


- 6027HT Tube Welding Tip, 1/8" 1/8" dia. hole, use with 1/8" diameter round rods
- 6029 Bigfoot Welding Tip, 1/8" Tip Same as 6027HT except larger foot
- 6030 Tube Welding Tip, 3/16" Tip 3/16" dia. hole, use with 3/16" dia. round rod
- 6031 Teardrop Welding Tip Flat tip that fits into corners
- 6020 Temperature Control Switch For all model 6 and 7 welders

For the standard 1/8" diameter welding rods, choose the 6027HT or the 6029. If you're using flat sticks, choose the 6031. For 3/16" diameter round rod, use the 6030 Speed Tip. Tips thread into all of Polyvance's airless heating elements. Made in USA.



**WELDING ACCESSORIES**

- 2045W Wire mesh - one 10" x 5" piece (50 sq. in.)
- 2045-10 Wire mesh - ten 10" x 5" pieces (500 sq. in.)
- 2045-100 Wire mesh - one hundred 10" x 5" pieces (5,000 sq. in.)
- 6124WB Stainless Steel Wire Brush - cleans welder tips
- 6481-1 1" Wide Aluminum Tape - 180 ft. long
- 6482 2" Wide Aluminum Tape - 1.5 mil thick - 10 yards
- 6485 2" Wide Aluminum Tape - 180 ft. long
- 6140 Tip Cleaning Brush - 1/8" diameter, for 6027HT and 6029 tips
- 6141 Tip Cleaning Brush - 3/16" diameter, for 6030 tip



**HOT AIR REPLACEMENT PARTS**

- 6050-NR1 Hot Air All Purpose Tip
- 6062ME Metal Hot Air Replacement Element
- 6100HW Hose & Wiring Assembly For 6053 and earlier hot air welders.
- 6101 Hose & Wiring Assembly For 6057 through 6085 hot air welders.
- 6150H Handle & Socket Assembly



For other hot air welder replacement and repair parts, go to [www.polyvance.com](http://www.polyvance.com)

